

REPORT NUMBER 6547318:1

REPORT PAGE 1 of 5 **REPORT DATE** 2023-05-17

PRINT DATE 2023-05-17

OWN ID N/A

BY

Interior Health - EPH

REPORT RECEIVER(S)

Interior Health - EPH mrobinson@365.sd58.bc.ca jeffrey.trieu@bccdc.ca daniel.tse@interiorhealth.ca

CANADA

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with a closed alpha-track detector (Radtrak^{2®}/Radtrak^{3®}) following the quality guidance given in CNRPP-AL-DF-v6.

The detector(s) arrived to Radonova Laboratories **2023-05-09**. They were measured **2023-05-15**.

Test data have been given by Melissa Robinson

Property data and address

MEASURE SITE ADDRESS
Merritt Central Elementary
1501 Voght Street
Merritt BC V1K 1B8

BUILDING ID

TYPE OF BUILDING: BUILDING YEAR: VENTILATION TYPE: FOUNDATION TYPE: PURPOSE OF TEST:

Test results

School

DETECTOR	MEASUREMENT PERIOD	DESCRIPTION / LOCATION	FLOOR	RADON RESULT
737494-5 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Central Elementary, Room 1		DNR
826849-2 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 2		< 23 Bq/m³
153404-9 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Central Elementary, Room 2		< 29 Bq/m³
950991-0 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 3		< 20 Bq/m³
177856-2 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 4		$51 \pm 16 \text{ Bq/m}^3$
838458-8 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 5		< 22 Bq/m³
202759-7 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Central Elementary, Room 6		21 ± 14 Bq/m³
164895-5 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 7		$22 \pm 16 \text{ Bq/m}^3$
212475-8 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Central Elementary, Room 8		< 29 Bq/m³

Comment to the results

Tryggve Rönnqvist (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.



RADONOVA INC.



REPORT NUMBER 6547318:1 REPORT PAGE

T PAGE PRINT DATE
2 of 5 2023-05-17

OWN ID N/A

BY

REPORT DATE

2023-05-17

Interior Health - EPH

REPORT RECEIVER(S)

Interior Health - EPH mrobinson@365.sd58.bc.ca jeffrey.trieu@bccdc.ca daniel.tse@interiorhealth.ca

CANADA

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with a closed alpha-track detector (Radtrak^{2®}/Radtrak^{3®}) following the quality guidance given in CNRPP-AL-DF-v6.

The detector(s) arrived to Radonova Laboratories **2023-05-09**. They were measured **2023-05-15**.

Test data have been given by Melissa Robinson

Property data and address

MEASURE SITE ADDRESS

Merritt Central Elementary

1501 Voght Street

Merritt BC V1K 1B8

BUILDING ID

DETECTOR	MEASUREMENT PERIOD	DESCRIPTION / LOCATION	FLOOR	RADON RESULT
661034-9 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Central Elementary, Room 9		< 29 Bq/m³
600184-6 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Central Elementary, Room 10		< 23 Bq/m³
613563-6 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 11		< 23 Bq/m³
905797-7 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Central Elementary, Room 12		< 27 Bq/m³
567524-4 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 13		< 20 Bq/m³
464705-3 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Central Elementary, Room 14		< 20 Bq/m³
188000-4 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 15		< 20 Bq/m³
144545-1 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Central Elementary, Room 16		< 23 Bq/m³
143161-8 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 17		28 ± 16 Bq/m³
665908-0 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Central Elementary, Room 18		16 ± 12 Bq/m³
631727-5 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 19		$50 \pm 16 \text{ Bq/m}^3$
579022-5 [Radtrak ² ®]	2023-01-03 – 2023-04-03	Central Elementary, Room 20		< 25 Bq/m³

Comment to the results



Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.



331.814.2200, help@radonova.com



REPORT NUMBER 6547318:1 REPORT PAGE

3 of 5

2023-05-17

PRINT DATE 2023-05-17

OWN ID N/A

BY

Interior Health - EPH

REPORT RECEIVER(S)

Interior Health - EPH mrobinson@365.sd58.bc.ca jeffrey.trieu@bccdc.ca daniel.tse@interiorhealth.ca

CANADA

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with a closed alpha-track detector (Radtrak^{2®}/Radtrak^{3®}) following the quality guidance given in CNRPP-AL-DF-v6.

The detector(s) arrived to Radonova Laboratories **2023-05-09**. They were measured **2023-05-15**.

Test data have been given by Melissa Robinson

Property data and address

MEASURE SITE ADDRESS
Merritt Central Elementary
1501 Voght Street
Merritt BC V1K 1B8

BUILDING ID

DETECTOR	MEASUREMENT PERIOD	DESCRIPTION / LOCATION	FLOOR	RADON RESULT
692666-1 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Central Elementary, Room 21		61 ± 16 Bq/m³
145248-1 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 22		$36 \pm 22 \text{ Bq/m}^3$
489649-4 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 23		23 ± 14 Bq/m³
691859-3 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 24		28 ± 16 Bq/m³
291386-1 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 25		< 23 Bq/m³
370777-5 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 26		DNR
165412-8 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 27		$38 \pm 18 \text{ Bq/m}^3$
974376-6 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 28		DNR
943679-1 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 29		74 ± 20 Bq/m³
208956-3 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 30		$43 \pm 16 \text{ Bq/m}^3$
305929-2 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Central Elementary, Room 31		$39 \pm 18 \text{ Bq/m}^3$
171693-5 [Radtrak²®]	2023-01-03 – 2023-04-03	Central Elementary, Room 32		67 ± 18 Bq/m³

Comment to the results

Tryggve Rönnqvist (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.



RADONOVA INC.



REPORT NUMBER 6547318:1 2023-05-17

REPORT PAGE 4 of 5 **PRINT DATE** 2023-05-17

OWN ID N/A

BY

Interior Health - EPH

REPORT RECEIVER(S)

Interior Health - EPH mrobinson@365.sd58.bc.ca jeffrey.trieu@bccdc.ca daniel.tse@interiorhealth.ca

CANADA

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with a closed alpha-track detector (Radtrak^{2®}/Radtrak^{3®}) following the quality guidance given in CNRPP-AL-DF-v6.

The detector(s) arrived to Radonova Laboratories **2023-05-09**. They were measured **2023-05-15**.

Test data have been given by Melissa Robinson

Property data and address

MEASURE SITE ADDRESS
Merritt Central Elementary
1501 Voght Street
Merritt BC V1K 1B8

BUILDING ID

DETECTOR	MEASUREMENT PERIOD	DESCRIPTION / LOCATION	FLOOR	RADON RESULT
995861-2 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Central Elementary, Room 33		58 ± 16 Bq/m³
377179-7 [Radtrak ^{2®}]	2023-01-03 — 2023-04-03	Central Elementary, Room 34		65 ± 18 Bq/m³

Comment to the results

Tryggve Rönnqvist (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.



RADONOVA INC.



REPORT NUMBER REPORT DATE

6547318:1 2023-05-17

REPORT PAGE PRINT DATE 5 of 5 2023-05-17

Measurement method: Closed alpha-track detector (Radtrak^{2®}/Radtrak^{3®})

OWN ID

The radon measurement was performed with a closed alpha-track detector following the quality assurance guidance given in CNRPP-AL-DF-v6. The detector container is manufactured from electrically conducting plastic. Through a small slit (filter), radon gas enters the detector. The track-detecting material (film) inside the detector is hit by alpha particles generated by the radon entering the container and the decay products formed from it. On the film, the alpha particles make small tracks which are enlarged through chemical etching and later analyzed via our proprietary Track-Etch(R) methodology to determine the radon exposure. Radonova Laboratories (P.O. Box 6522, SE-751 38 Uppsala, Sweden) is accredited (no. 1489) by SWEDAC to conduct radon-gas measurements using the closed alpha-track detector method. The analysis equipment is checked daily and the detectors are calibrated at regular intervals. CNRPP License CRT 201475.

Measured radon concentrations

For each detector, the measured value of the radon concentration is provided. For each value an uncertainty associated with the measurement to a 95% confidence level is also provided. For example a measurement result of 200 ± 30 Bq/m³ means that the radon concentration is most likely contained in the range 170 - 230 Bq/m³. If the start or end date of the measurement has not been provided, the radon concentration cannot be calculated. In such cases, the total exposure in kBqh/m³ will be reported. The average radon concentration can be calculated by dividing the total exposure with the number of measured hours and multiplying that result with 1000. The reported measured values are related to the detectors as received by Radonova Laboratories. Detector deployment is not performed by Radonova Laboratories. Measurement information such as monitoring period (dates) and placement location is provided to Radonova Laboratories by the end user. The presented results apply only to the samples tested.

Codes on non-reportable detectors

DNR Not Reported – Detector Not Returned
 VTW Not Reported – Visibly Tampered With
 FBD Not Reported – Film Broken or Damaged

LIL Not Reported – Lost in Lab

DTO Not Reported – Detector Too Old

Measurement method versions used when the report was created

CNRPP-AL-DF-v6,October 2018, Quality Control and Quality Assurance Manual for Radon Sampling and Analysis ISO 11665-4:2021, Measurement of radioactivity in the environment — Air: radon-222

Radon measurements in Schools and Public Buildings

Health Canada recommends that the radon test performed in a home or public building be a long-term measurement. Health Canada does not recommend a test of duration less than one month. A minimum of 3 months is recommended and 12 months is optimum. If the long-term measurement results are below 200 Bq/m³, the average annual concentration in the home or building is probably below 200 Bq/m³ and further measurements are not necessary and remedial action is not recommended. If the measured concentration is above 200 Bq/m³ in schools, a follow-up short-term measurement is recommended in order to estimate the radon concentration during school hours:

Schools_hours_concentration = Long_term_concentration * (Short_term_schools_hours / Short_term_average).

If the long term average radon concentration during school hours is above 200 Bq/m³, remedial action is recommended (see the Health Canada Publication Guide for Radon Measurements in Public Buildings for more information)

Workplaces

Radon in workplaces should be handled according to the Canadian Guidelines for the Management of Naturally Occuring Radioactive Materials (NORM).

Average Annual Concentrations	NORM Program Classification
800 - 3000 Bq/m³	Radiation Protection Management
200 - 800 Bq/m³	NORM Management
< 200 Bq/m³	Unrestricted

Signature on the report

With the signature on the report, the person responsible for the radon analysis at Radonova Laborat procedures follows the guidance in accordance with CNRPP-AL-DF-v6 and that the demands from SWEDAC

Measurement information displayed in italics on report has been provided by the customer.

