

REPORT NUMBER 6547317:1

REPORT PAGE 1 of 4 REPORT DATE 2023-05-17

PRINT DATE 2023-05-17

OWN ID N/A

BY

Interior Health - EPH

REPORT RECEIVER(S)

Interior Health - EPH mrobinson@365.sd58.bc.ca jeffrey.trieu@bccdc.ca daniel.tse@interiorhealth.ca

CANADA

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with a closed alpha-track detector (Radtrak^{2®}/Radtrak^{3®}) following the quality guidance given in CNRPP-AL-DF-v6.

The detector(s) arrived to Radonova Laboratories **2023-05-09**. They were measured **2023-05-16**.

Test data have been given by Sonya Zakall

Property data and address

MEASURE SITE ADDRESS
Diamond Vale Elementary
2675 Coldwater Ave
Merritt BC V1K 1B2

BUILDING ID

TYPE OF BUILDING: BUILDING YEAR: VENTILATION TYPE: FOUNDATION TYPE: PURPOSE OF TEST: School

Test results

DETECTOR	MEASUREMENT PERIOD	DESCRIPTION / LOCATION	FLOOR	RADON RESULT
217407-6 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 1		54 ± 16 Bq/m³
924725-5 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Diamond Vale Elementary, 2		< 27 Bq/m³
503756-9 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 3		$28 \pm 18 \text{ Bq/m}^3$
642515-1 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Diamond Vale Elementary, 3		$53 \pm 20 \text{ Bq/m}^3$
137839-7 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 4		$53 \pm 18 \text{ Bq/m}^3$
820859-7 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Diamond Vale Elementary, 5		$19 \pm 14 \text{ Bq/m}^3$
205098-7 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 6		$50 \pm 18 \text{ Bq/m}^3$
787012-4 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Diamond Vale Elementary, 7		$62 \pm 16 \text{ Bq/m}^3$
988894-2 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Diamond Vale Elementary, 8		$50 \pm 18 \text{ Bq/m}^3$

Comment to the results

Tryggve Rönnqvist (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.



RADONOVA INC.



REPORT NUMBER 6547317:1

REPORT PAGE
2 of 4

2023-05-17 **PRINT DATE**

REPORT DATE

2023-05-17 OWN ID

> N/A BY

Interior Health - EPH

REPORT RECEIVER(S)

Interior Health - EPH mrobinson@365.sd58.bc.ca jeffrey.trieu@bccdc.ca daniel.tse@interiorhealth.ca

CANADA

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with a closed alpha-track detector (Radtrak^{2®}/Radtrak^{3®}) following the quality guidance given in CNRPP-AL-DF-v6.

The detector(s) arrived to Radonova Laboratories **2023-05-09**. They were measured **2023-05-16**.

Test data have been given by Sonya Zakall

Property data and address

MEASURE SITE ADDRESS
Diamond Vale Elementary
2675 Coldwater Ave
Merritt BC V1K 1B2

BUILDING ID

DETECTOR	MEASUREMENT PERIOD	DESCRIPTION / LOCATION	FLOOR	RADON RESULT
986807-6 [Radtrak²®]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 9		57 ± 18 Bq/m³
271746-0 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Diamond Vale Elementary		65 ± 16 Bq/m³
304118-3 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 11		24 ± 14 Bq/m³
983416-9 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Diamond Vale Elementary, 12		53 ± 16 Bq/m³
295217-4 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 12		50 ± 18 Bq/m³
316592-5 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 13		$40 \pm 16 \text{ Bq/m}^3$
241099-1 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 14		44 ± 16 Bq/m³
824006-1 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 15		65 ± 18 Bq/m³
194669-8 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary		$30 \pm 18 \text{ Bq/m}^3$
307301-2 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Diamond Vale Elementary, 17		< 27 Bq/m³
940224-9 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Diamond Vale Elementary, 18		39 ± 18 Bq/m³
158556-1 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 19		29 ± 16 Bq/m³

Comment to the results

Tryggve Rönnqvist (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.



RADONOVA INC.



REPORT NUMBER 6547317:1

REPORT PAGE 3 of 4 **REPORT DATE** 2023-05-17

PRINT DATE 2023-05-17

OWN ID N/A

BY

Interior Health - EPH

REPORT RECEIVER(S)

Interior Health - EPH mrobinson@365.sd58.bc.ca jeffrey.trieu@bccdc.ca daniel.tse@interiorhealth.ca

CANADA

RADON MONITORING REPORT

Description of the measurement

The measurement was performed with a closed alpha-track detector (Radtrak^{2®}/Radtrak^{3®}) following the quality guidance given in CNRPP-AL-DF-v6.

The detector(s) arrived to Radonova Laboratories **2023-05-09**. They were measured **2023-05-16**.

Test data have been given by Sonya Zakall

Property data and address

MEASURE SITE ADDRESS
Diamond Vale Elementary
2675 Coldwater Ave
Merritt BC V1K 1B2

BUILDING ID

DETECTOR	MEASUREMENT PERIOD	DESCRIPTION / LOCATION	FLOOR	RADON RESULT
392719-1 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 20		31 ± 20 Bq/m ³
949703-3 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 21		$43 \pm 16 \text{ Bq/m}^3$
182558-7 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Diamond Vale Elementary, 23		$40 \pm 16 \text{ Bq/m}^3$
253089-7 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 22		41 ± 16 Bq/m³
438035-8 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Diamond Vale Elementary, 24		99 ± 22 Bq/m³
791033-4 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 25		54 ± 16 Bq/m ³
817309-8 [Radtrak ^{2®}]	2023-01-03 - 2023-04-03	Diamond Vale Elementary, 26		$36 \pm 16 \text{ Bq/m}^3$
218564-3 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 27		$74 \pm 20 \text{ Bq/m}^3$
722101-3 [Radtrak ^{2®}]	2023-01-03 – 2023-04-03	Diamond Vale Elementary, 28		$40 \pm 18 \text{ Bq/m}^3$

Comment to the results

Tryggve Rönnqvist (Electronically signed)

Signature Radonova Laboratories Laboratory Measurement Specialist

This report may only be reproduced in full, unless issuing laboratory has given prior written approval.



RADONOVA INC.



REPORT NUMBER

REPORT DATE

6547317:1

2023-05-17

REPORT PAGE 4 of 4 **PRINT DATE** 2023-05-17

Measurement method: Closed alpha-track detector (Radtrak^{2®}/Radtrak^{3®})

OWN ID

The radon measurement was performed with a closed alpha-track detector following the quality assurance guidance given in CNRPP-AL-DF-v6. Whe detector container is manufactured from electrically conducting plastic. Through a small slit (filter), radon gas enters the detector. The track-detecting material (film) inside the detector is hit by alpha particles generated by the radon entering the container and the decay products formed from it. On the film, the alpha particles make small tracks which are enlarged through chemical etching and later analyzed via our proprietary Track-Etch(R) methodology to determine the radon exposure. Radonova Laboratories (P.O. Box 6522, SE-751 38 Uppsala, Sweden) is accredited (no. 1489) by SWEDAC to conduct radon-gas measurements using the closed alpha-track detector method. The analysis equipment is checked daily and the detectors are calibrated at regular intervals. CNRPP License CRT 201475.

Measured radon concentrations

For each detector, the measured value of the radon concentration is provided. For each value an uncertainty associated with the measurement to a 95% confidence level is also provided. For example a measurement result of 200 ± 30 Bq/m³ means that the radon concentration is most likely contained in the range 170 - 230 Bq/m³. If the start or end date of the measurement has not been provided, the radon concentration cannot be calculated. In such cases, the total exposure in kBqh/m³ will be reported. The average radon concentration can be calculated by dividing the total exposure with the number of measured hours and multiplying that result with 1000. The reported measured values are related to the detectors as received by Radonova Laboratories. Detector deployment is not performed by Radonova Laboratories. Measurement information such as monitoring period (dates) and placement location is provided to Radonova Laboratories by the end user. The presented results apply only to the samples tested.

Codes on non-reportable detectors

DNR Not Reported – Detector Not Returned
 VTW Not Reported – Visibly Tampered With
 FBD Not Reported – Film Broken or Damaged

LIL Not Reported – Lost in Lab

DTO Not Reported – Detector Too Old

Measurement method versions used when the report was created

CNRPP-AL-DF-v6,October 2018, Quality Control and Quality Assurance Manual for Radon Sampling and Analysis ISO 11665-4:2021, Measurement of radioactivity in the environment — Air: radon-222

Radon measurements in Schools and Public Buildings

Health Canada recommends that the radon test performed in a home or public building be a long-term measurement. Health Canada does not recommend a test of duration less than one month. A minimum of 3 months is recommended and 12 months is optimum. If the long-term measurement results are below 200 Bq/m³, the average annual concentration in the home or building is probably below 200 Bq/m³ and further measurements are not necessary and remedial action is not recommended. If the measured concentration is above 200 Bq/m³ in schools, a follow-up short-term measurement is recommended in order to estimate the radon concentration during school hours:

Schools_hours_concentration = Long_term_concentration * (Short_term_schools_hours / Short_term_average).

If the long term average radon concentration during school hours is above 200 Bq/m³, remedial action is recommended (see the Health Canada Publication Guide for Radon Measurements in Public Buildings for more information)

Workplaces

Radon in workplaces should be handled according to the Canadian Guidelines for the Management of Naturally Occuring Radioactive Materials (NORM).

Average Annual Concentrations	NORM Program Classification
800 - 3000 Bq/m³	Radiation Protection Management
200 - 800 Bq/m³	NORM Management
< 200 Bq/m³	Unrestricted

Signature on the report

With the signature on the report, the person responsible for the radon analysis at Radonova Laborat procedures follows the guidance in accordance with CNRPP-AL-DF-v6 and that the demands from SWEDAC

Measurement information displayed in italics on report has been provided by the customer.

